



Note: Drawing not to scale

Tolerances:  
X.XX ±0.020

FIG. 1

All dimensions are in inches. **The exterior dimensions shown are maximums.**  
All connectors and solder terminals shall be mounted on the surfaces shown.  
Final positioning shall be determined by the manufacturer.